





DESGUACES


LA TORRE

museo de automoción





torrejón
de la calzada

vista satélite de la península desde canarias







































































exposición permanente

exposiciones y eventos temporales

escuela-taller


centro de documentación


otras dotaciones


administración y atención al público

instalaciones, servicios y almacenes


aparcamiento









PLANTA -1, COTA -7.50
ESCUELA-TALLER




PLANTA -1, COTA -7.50
SERVICIOS




PLANTA -1, COTA -7.50
INSTALACIONES




PLANTA -1, COTA -7.50
EXPOSICIONES




PLANTA -1, COTA -7.50
OTROS USOS




PLANTA -1, COTA -7.50
COMUNICACIONES




PLANTA -1, COTA -7.50
SERVICIOS



PLANTA -1, COTA -7.50
INSTALACIONES



PLANTA 0, COTA +0.00
EXPOSICIONES




PLANTA 0, COTA +0.00
OTROS USOS



PLANTA 0, COTA +0.00
COMUNICACIONES




PLANTA 0, COTA +0.00
SERVICIOS




PLANTA 0, COTA +0.00
INSTALACIONES




PLANTA 1, COTA +7.50
COLECCIÓN PERMANENTE




PLANTA 1, COTA +7.50
EXPOSICIONES




PLANTA 1, COTA +7.50
COMUNICACIONES




PLANTA 1, COTA +7.50
VACÍOS




PLANTA 1, COTA +7.50
INSTALACIONES




ENTREPLANTA, COTA +15.00
LOCALES DE USO INTERNO




ENTREPLANTA, COTA +15.00
COMUNICACIONES




ENTREPLANTA, COTA +15.00
INSTALACIONES





ENTREPLANTAS, COTA +21.00 Y +24.00
COMUNICACIONES





ENTREPLANTAS, COTA +21.00 Y +24.00
INSTALACIONES
















0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150 160 170 180 190 200 210 220 230 240 250


PLANTA -1




0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150 160 170 180 190 200 210 220 230 240 250


PLANTA 0













VERANO

INVERNO









John Chamberlain

A Catalogue Raisonné
of the Sculpture
1954–1985





**RECICLAJE
FERRICO**



The Vehicle Recycling Process



Vehicle is purchased after being taken off the road usually due to accident damage.




All fluids are drained from vehicle in a special facility designed to contain all toxic materials from contaminating the soil.




Vehicle is placed on safety stands in the yard and entered into inventory.




Parts removed by customers with their own tools.



Once all of the usable parts have been sold and the vehicle is 'parted-out' it is flattened in a large crushing unit.



Flattened vehicles are transported off-site for further processing.



Flattened vehicles are shredded and separated into; metal, glass, plastic and fabric for further recycling. At this point they are mostly re-introduced back into the product cycle where they can start the process all over again.






















**MOTORES
CAJAS DE CAMBIO**

**RECICLAJE
FERRICO**





PRODUCCIÓN
VEHICULOS 'NUEVOS'



UTILIZACIÓN



REPARACIÓN



DESECHO



COLECCIONISMO
FIN DE VIDA ÚTIL



CICLO INDUSTRIAL
CERRADO























COGENERACION

RECICLAJE







